DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-023875

Address: 333 Burma Road **Date Inspected:** 13-May-2011

City: Oakland, CA 94607

OSM Arrival Time: 1900 **Project Name:** SAS Superstructure **OSM Departure Time:** 700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: See below **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes N/A **Delayed / Cancelled:** No

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Kelly Leavitt, was present during the times noted above for random observations relative to the work being performed.

Trial Assembly

This QA Inspector observed the following work in progress for Trial Assembly.

ZPMC was using the Shielded Metal Arc Welding (SMAW) process.

ZPMC QC is identified as Xie Ming Feng and ABF QA Sha Zhi.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector.

Components; OBG 13CE PCMK: SEG3019AE

Weld No: 066,013,020,027,034,041

Welder: 215553

WPS-B-P-2213-TC-U4b-FCM-1

Components; OBG 14E PCMK: SEG3019AE Weld No: 005,012,019,026

Welder: 044779

WPS-B-P-2213-TC-U4b-FCM-1



WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Components; OBG 13CE

PCMK: CA3014A Weld No: 159,124,162

Welder: 058102

WPS-B-P-2213-B-U2-FCM-1

This QA Inspector observed the following work in progress for Trial Assembly.

ZPMC was using the Flux Core Arc Welding (FCAW) process.

ZPMC QC is identified as Xie Ming Feng and ABF QA Sha Zhi.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS). Listed below are the locations that were identified by this QA inspector.

Components; OBG 13CE

PCMK: SEG3011E Weld No: 259,262 Welder: 050977

WPS-B-T-2233-ESAB

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

"No relevant conversations."

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact James Devey 1500026784, who represents the Office of Structural Materials for your project.

| Inspected By: | Leavitt, Kelly | Quality Assurance Inspector |
|---------------|----------------|-----------------------------|
| Reviewed By: | Riley,Ken | QA Reviewer |